



Supplies Needed

- #63815067 Copper Beading Wire Mix, 22 Gauge, 12 pc. (1 pk)
- #69991587 In Bloom Black Seed Bead/E-Bead Mix Assortment (1 pk)
- #34708281 Silver Metal Bead Caps, 30 pc. (1 pk)
- #63716351 Round 10mm Black Glass Bead Strand, 15.5" (1 pk)
- #63715483 Round & Rondelle AB Faceted Bead Strand, 102 pc. (1 pk)
- #34719052 Silver 3" Head Pins, 36 pc. (1 pk)

Tools & Additional Supplies Needed

- Wire Cutters
- Round Nose Pliers
- Nylon Jaw Wire Pliers (optional but helpful)
- Ruler

Techniques to Know

Form a Loop

Instructions:

1. Cut an 8" length of black copper wire. Form a tiny loop on one end of the wire.
2. Run fingers along the length of the wire, or use nylon jaw wire pliers, to straighten out the wire. String on the following: one large black e-bead, two black bugle beads, one large black e-bead, one medium red AB faceted bead, one large black e-bead, two black bugle beads, one large black e-bead, one medium red AB faceted bead, and three black bugle beads.
3. Use round nose pliers to form a tight loop snug up against the last bugle bead added in the previous step.
4. Repeat step 2, in reverse order.
5. Repeat step 3.
6. *Repeat steps 1-5, a total of four times. These beaded wire strands are the legs of the beaded spider.
7. Cut off the head on the end of a 3" head pin. Form a small loop on one end of the head pin. Slide the following onto the head pin: a small silver star bead cap, 10mm black glass bead, and a small silver star bead cap so the bead caps hug the bead.
8. Next, slide the middle loop on each set of legs onto the head pin.

9. Slide on another small silver star bead cap and a large red AB faceted bead so the bead cap hugs the bead from behind. Form a snug loop after the large red AB faceted bead and trim off any remaining head pin stem.
10. Arrange legs, on each side of the spider, so the spider stands up.

***Spider legs can be made longer or shorter by adding more bugle beads onto the legs.**

SKILL LEVEL: Advanced Beginner

APPROXIMATE CRAFTING TIME: 1 Hr.